

North Amherst Library South Wall Repair

October 2020

Pictures:

The next three pictures show the where the first floor support beam has been cut to install stairs from the first floor to the basement. Previous access to the basement was from the outside with no connection to the first floor.

Picture #1



Picture #2. There should be 2 floor joist in this space resting on the support beam. The beam section and floor joist were removed for the stairs.



Picture #3



The next three pictures show the shoring that was installed and some follow on weather proffing.

Picture 4



Picture 5



Picture 6

